

# Certificate of Calibration

## Beaverton Service Center

<b>Certificate Number:</b> 316416		<b>Calibration Date:</b> 06-Feb-2017
<b>Data Type:</b> Found-Left		<b>Calibration Due:</b> 06-Feb-2018
<b>Result Summary:</b> In Tolerance		<b>Certificate Date:</b> 06-Feb-2017
<b>Manufacturer:</b> Fluke		<b>Temperature:</b> 23.0 °C
<b>Model:</b> 70 III		<b>Humidity:</b> 26.4 %
<b>Serial Number:</b> 73950580		
<b>Description:</b> Multimeter		

<b>Procedure:</b> Fluke 70-3: (1 year) CAL VER /5520A	<b>Revision:</b> 1.2
<b>Customer:</b> STATE OF WASHINGTON	
<b>City:</b> SEATTLE	<b>Country:</b> US
<b>State:</b> WA	
<b>Purchase Order:</b> CCS WASHINGTON ST PATROL	<b>RMA:</b> 31199547

This calibration is traceable to the International System of Units (SI), through National Metrology Institutes (NIST, PTB, NRC, NPL, etc.), radiometric techniques, or natural physical constants. This certificate applies only to the item identified and shall not be reproduced other than in full, without the specific written approval by Fluke Corporation. Calibration certificates without signature are not valid. The calibration has been completed in accordance with Fluke Electronics Corporation Quality System Document 111.0 Revision 118 8/2014 and/or Fluke 17025 Quality Manual QSD 111.41 Revision 005 9/2014.

The Data Type found in this certificate must be interpreted as:

- As - Found Calibration data collected before the unit is adjusted and / or repaired.
- As - Left Calibration data collected after the unit has been adjusted and / or repaired.
- Found-Left Calibration data collected without any adjustment and / or repair performed.



*Tracy Wright*  
 TRACY WRIGHT  
 Issued By

**Certificate Number:** 316416**Date of Calibration:** 06-Feb-2017**Standards Used**

<b>Asset</b>	<b>Description</b>	<b>Cal-Date</b>	<b>Cal-Due</b>
16533	Fluke 5522A Calibrator	31-May-2016	31-May-2017